

Coding Rule of Trunk Cable

FL	PA	B	C	D	E	FFF	G	-	H	III	-	JJ
Cable Type T Trunk cable		Polarity A key up to key down B key up to key up Notes: Recommend Type-B		Termination End B 1 MPO low loss MM-male 2 MPO low loss MM-female 3 MPO/APC SM-male 4 MPO/APC SM-female 5 MTP low loss MM-male 6 MTP low loss MM-female 7 MTP/APC SM-male 8 MTP/APC SM-female		Jacket Type E OFNR F OFNR + end B pulling eye G LSFRZH H LSFRZH + end B pulling eye X OFNP Y OFNP + end B pulling eye		Length 001-XXX				
Fiber Type M MaxCap Safe 300 BI-OM3 50/125 μ m C MaxCap Safe 550 BI-OM4 50/125 μ m T TeraSafe 9/125 μ m BI-OS2 / G.657.A1 S TeraSafe Plus 9/125 μ m SBI-OS2 / G.657.A2		Termination End A 1 MPO low loss MM-male 2 MPO low loss MM-female 3 MPO/APC SM-male 4 MPO/APC SM-female 5 MTP low loss MM-male 6 MTP low loss MM-female 7 MTP/APC SM-male 8 MTP/APC SM-female		Fiber Count 081 8C MPO x 1 121 12C MPO x 1 242 12C MPO x 2 * 241 24C MPO x 1 Notes: Recommend 12c MPO, 24c branch to 2*12c MPO (24c need remark)		Unit of Measure F Feet M Meters		Sheath Color YL Yellow (OS2) OR Orange (OM2) AQ Aqua (OM3/OM4) default EV Erika Violet (OM4) another option LG Lime Green (OM5)				

