



FastLinkcabsys 预端接主干光缆编码规则

FL - PA	B	C	D	E	FFF	G	-	H	III
Cable Type T Trunk cable	Polarity A key up to key down B key up to key up 备注: 建议采用Type-B	Termination End B 1 MPO low loss MM-male 2 MPO low loss MM-female 3 MPO/APC SM-male 4 MPO/APC SM-female 5 MTP low loss MM-male 6 MTP low loss MM-female 7 MTP/APC SM-male 8 MTP/APC SM-female	Termination End A 1 MPO low loss MM-male 2 MPO low loss MM-female 3 MPO/APC SM-male 4 MPO/APC SM-female 5 MTP low loss MM-male 6 MTP low loss MM-female 7 MTP/APC SM-male 8 MTP/APC SM-female	Jacket Type E OFNR F OFNR + end B pulling eye G LSFRZH H LSFRZH + end B pulling eye X OFNP Y OFNP + end B pulling eye	Fiber Type M MaxCap Safe 300 BI-OM3 50/125μm C MaxCap Safe 550 BI-OM4 50/125μm T TeraSafe 9/125μm BI-OS2 / G.657-A1 S TeraSafe Plus 9/125μm SBI-OS2 / G.657-A2	Fiber Count 081 8C Fiber x 1 121 12C Fiber x 1 242 12C Fiber x 2	Unit of Measure F Feet M Meters	Length 001-XXX	

