

SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

SGS Bldg., No. 4, Jianghao Industrial Park, No. 430, Jihua Road, Bantian, Longgang District, Shenzhen, China P.C:518049 Tel:86 755 25328888 / 83114358 Fax:86 755 83139706 / 83139732

INSPECTION REPORT

To :	ENCHANTE LITES LLC	Date:	06-Jul-	2021
Att :	CINDY			
From :	Jessie Zhou	E-mail :	Jessie	zhou@sgs.com

SGS File No.:	HKSZX4855817	Product family view
Buyer :	ENCHANTE LITES LLC	
Supplier :	TOPWAY CHINA	
Manufacturer :	FOSHAN NANHAI SHENGHUI STAINLESS STEEL PRODUCTS FACTORY	
Style Number:	31100611 31100621 31100631 31100641 31100651 31100661 31100671	
Product description:	Handicapped Restroom Grab Bar 12" Handicapped Restroom Grab Bar 24" Handicapped Restroom Grab Bar 36" Handicapped Restroom Grab Bar 54cm Handicapped Restroom Grab Bar 12" Handicapped Restroom Grab Bar 18" Handicapped Restroom Grab Bar 24"	2021/07/06
P.O. Number:	#75888 #75889	
L/C Number:	N/A	
Service performed :	FRI	
Inspection Date :	06- <mark>Jul-202</mark> 1	
Inspection Location :	Foshan, Guangdong, China]

Inspection Criteria

Reference sample provided by	Not Available			
Client instruction/specification	Yes			
SGS WI number	P-INSP-WI-HL-102			
Other	Nil			

Overall Inspection Conclusion:

Subject to client's evaluation

Inspector: Shouyi Luo

Factory Representative:

"This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's more than the limits of Client's more t

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law."



Inspection Summary:

1. Quantity :	Conform				
2. Style, color :	Conform				
3. Workmanship appearance / function :	Conform				
4. Data measurement / field tests:	Subject to client's evaluation				
5. Packing :	Conform				
6. Marking / label :	Conform				
Problem Remark:					
-There was no ref-sample for compare during the inspection.					
-For carton drop, no visible damage was found on the package and product.					

Quantity: 1.

Conform

No	Style / Item/ Article	P.O. No.	Order Qty.	Inspection Qty. (Presented Qty. for insp.)		Number of Cartons	
711000				Packed	Not Packed	Packed	Not packed
1	31100611	#75888	120	0	0	6	0
2	31100621	#75888	120	0	0	6	0
3	31100631	#75888	120	0	0	6	0
4	31100641	#75888	120	0	0	12	0
5	31100651	#75888	120	0	0	6	0
6	31100661	#75888	120	0	0	6	0
7	31100671	#75888	120	0	0	6	0
8	31100611	#75889	380	0	0	19	0
9	31100621	#75889	380	0	0	19	0
10	31100631	#75889	380	0	0	19	0
11 🖣	31100641	#7588 9	380	0	0	38	0
12	31100651	#75889	380	0	0	19	0
13	31100661	<mark>#75889</mark>	380	0	0	19	0
14	31100671	#75889	380	0	0	19	0
		Total:	3500	0	0	200	0

2. Style & Color Conformity:

Conform

Comments: -Refer to photo for details.

3. Workmanship Appearance / Functional Inspection Findings:

Within AQL

Inspector: Shouyi Luo Factory Representative:

"This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law."

SG

Report No.: SZXWT01163829

Inspection Method Applied:

ANSI/ASQ Z1.4 2003 (R2018), Single sampling plans for normal inspection Level I Sample size: 80	3		
Acceptance Quality Limit (AQL) for: Critical: Not Major: 2.	5	Minor: 4.0	
Defect description	Critical	Major	Minor
31100611 S/S: 11			
Dark mark on the surface	0	0	1
31100621 S/S: 11			
Dent mark on the surface	0	0	1
31100631 S/S:11			
No defect found	0	0	0
31100641 S/S: 11			
No defect found	0	0	0
31100651 S/S: 12			
No defect found	0	0	0
31100661 S/S: 12			
Dirty mark on the surface & Dent mark on the surface on 1pcs	0	1	0
Scratch mark on the surface	0	0	2
04400074 0/0 12			
31100671 S/S: 12	0	0	4
Black mark on the surface	0	0	1
Dirty mark on the surface	0	0	1
	0	4	6
Total defectives:	0	1 5	6 7
Maximum allowed:	U	5	/

Defect photos :

Shouyi Luo Inspector:

Factory Representative:

"This document is issued by the Company under its General Conditions of Service accessible at <u>http://www.sgs.com/en/Terms-and-Conditions.aspx</u>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law."






4. Product-Specific Data Measurement / Field Test on Reduced Sample Size: Not Conform

Check points	Qty	Test Result	Specification/Tolerance
Barcode scan	3pcs/ item	Pass	1

Inspector: Shouyi Luo Factory Representative:

"This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law."





Inspector: Shouyi Luo


Factory Representative:

"This document is issued by the Company under its General Conditions of Service accessible at <u>http://www.sgs.com/en/Terms-and-Conditions.aspx</u>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law."

[Rev.08: Mar.24th.2020]





Inspector: Shouyi Luo

Factory Representative:

"This document is issued by the Company under its General Conditions of Service accessible at <u>http://www.sgs.com/en/Terms-and-Conditions.aspx</u>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law."



Printed on the outer carton 31100611 31100611 45x42x38.5cm/14.3kg 45x41x37.5cm/13.8kg 31100621 31100621 71.5x43x38.5cm/20.7kg 71.5x45x37.5cm/19.5kg 31100631 31100631 102x46x38cm/27.0kg 102x45x37.5cm/26.5kg 31100641 31100641 Size and weight of the outer carton 1ctn 63.5x39x47cm/10.8kg 63.5x38x46.5cm/10.5kg 31100651 31100651 45x42x38cm/20.5kg 45x41x37.5cm/19.8kg 31100661 31100661 56.5x46x38.5cm/23.6kg 56x45x37.5cm/23.5kg 31100671 31100671 46x71.5x38cm/26.8kg 45x71.5x37.5cm/26.3kg For carton drop, no visible Carton drop test 1ctn damage was found on the 76/61/46cmx10times backage and product. 5. Packing: 5.1 Individual packing conformity : Subject to client's evaluation Comments: -Refer to photo for details. 5.2 Inner packing conformity : Conform Comments:

-Refer to photo for details.

5.3 Export packing conformity

-Refer to photo for details.

Comments:

Conform

5.4 Samples selected from carton numbers: Total opened 14 for inspection. There was not carton number on the outer carton. 31100611: 3,18 31100621: 3,19 31100631: 2,13 31100641: 9,33 31100651: 5,9

Inspector: Shouyi Luo

Factory Representative:


"This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and

instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law."



31100661: 2,19 31100671: 5,9

6. Marking / Label:



Inspector: Shouyi Luo

Factory Representative:

"This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's

Any holder of this document is advised that information contained hereon reflects the Company's indings at the time of its intervention only and within the times of client s instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law."